BID OPENING CERTIFICATION RECORD

Date of Bid Walk:	Due Date:	HNS #:		
	Address		PBE Amount	
PUBLIC BODY ESTIMATE	1836 Ir	maj	\$33,709	
PUBLIC BODY ESTIMATE:				
PUBLIC BODY ESTIMATE:			+.15 \$ 38,7	65
PUBLIC BODY ESTIMATE:			<u>15 5 28,6</u>	53
PUBLIC BODY ESTIMATE:				
	ВП	WALK ATTENDEES		
				· 11-11-11
	-		11.000	
			BIDDERS	.
		\checkmark	BIDDEK3	X
Address:		Good will	Yeshua's JPGROUP	JINSPER
1. 1836 I	V m a	# 37973 %	\$34900 Fr \$31,909, Fr	# 41 495 %
1. Company		<u> </u>	51018	
2				
3				•
4				/
4				
5				
This is to certify that bids fo Office located at 600 E. Trac	-		d and read aloud in the Neighborhood &	Business Services
Office located at 600 E. Had	ie street, Charlotte, No		TALL	All.
Bids Opened By:	SW PL	Bids Recorde		RIMONDO
Witnessed By:		Date:	5/10/18	<u> </u>
·			and 15% below the public body cost esti	mate. As a
general rule, the lo	west responsive bid is	recommended to the pr	operty owner for consideration.	



CITY OF CHARLOTTE

NEIGHBORHOOD & BUSINESS SERVICES

Invitation to Bid

NOTE: Contractors are not authorized to visit the property before or after the bid walk, without being accompanied by the City's Rehabilitation Specialist.

Documents included in Package:

- 1) Instruction to Bidders
- 2) Specs by Location/Trade (Scope of Work)
- 3) Subcontractor Certifications (if applicable)
- 4) Floor Plan / Site Drawing (if applicable)

Bid Walk & Bid Opening:

Project Address: 1836 Irma St.	S	SAFE HOME CHARLOTTE
Call project manager for full address		
Bid Walk: Thursday- 5/3	/18 at	1 pm
Bid Opening: Thursday- 5	/ 10 /18 a	t 2 pm
Client Name: Linda Moore		Contact Number: Do not Contact
Project Manager: Chuck Hitsman		Contact Number: 704-336 3495

Bid Walk and Bidding Instructions:

All bid walks are mandatory.

Lead Risk Assessment will be available for review at Bid-Walk. Copy given to Awarded Contractor.

If you are going to be late the policy is the following:

Contact me BEFORE the start time if you are going to be late. If you are going to be more than 10 minutes late, we will proceed without you and you will not be permitted to bid.

The day of a bid walk the best way to reach me is at <u>Charles Hitsman</u>(cell # 704-622 1685).

Bids must be received by the date, time and place specified. All others will be considered non responsive and disqualified.



CITY OF CHARLOTTE

NEIGHBORHOOD & BUSINESS SERVICES

The Bids will be opened at 600 East Trade St. immediately following the above due date and time.

Company Acknowledgement:
The undersigned, having become thoroughly familiar with the terms, conditions, limitations, and provisions of the housing improvement work to be performed at 1836 Irma St. to be funded through the City of Charlotte Neighborhood & Business Services, in addition, having fully inspected the site in all particulars, hereby proposes and agrees to fully perform the work within the time stated and in strict accordance with the proposed contract documents including furnishing of any and all labor and materials, and to do all work required to complete said Work in accordance with the advised respective contractual, for the sum of money: All labor, materials, services and equipment necessary for the completion of the Work shown on the Drawings and in the Specifications:
Written total
Specs Dated: 04/18/18 Number of Pages: 7
Project Minimum Start date: TBD Project Completion Deadline: TBD
Please Print and Sign:
Company Name/Firm: TP GRup Control, r
Authorized Representative Name: J GRup Cry (ioh, 72 Authorized Representative Name: 74 Authorized R
Signature: Date: 5/9/18

G:\SELECTIVE REHAB TEAM\forms\bid forms and documents\Invitation to bid WARREN



CITY OF CHARLOTTE
NEIGHBORHOOD & BUSINESS SERVICES



CITY OF CHARLOTTE

NEIGHBORHOOD & BUSINESS SERVICES

Requirements For Bidders

The City awards rehabilitation bids to the lowest responsive and responsible bidder. A responsible bidder for the safe home program is one who:

- 1) Is a licensed general contractor in the State of North Carolina;
- 2) Has an Renovate, Repair & Paint Certification (http://www2.epa.gov/lead/renovation-repair-and-painting-program);
- 3) Is not listed on a local, state or federal debarment list;
- 4) Carries an appropriate amounts of insurance;
- 5) Can provide references verifying the contractor has completed work of a similar scope in a good workmanship like manner or successfully completed prior work for the Safe Home program. Referenced work must have been completed in one year or less from date of this invitation to bid.

A responsive bidder must:

- 1) Submit all requested documentation on time;
- 2) Meet the above requirements for responsibility at the time of bid submittal;
- 3) Have the capacity to meet the required schedule for the project.
- 4) Existing rehab projects contracted by the contractor must be on schedule.

The City reserves the right to waive any minor informalities or irregularities, which do not go to the heart of the bid submittal or prejudice other offers, or to reject, for good and compelling reasons, any or all bid submittals.

Charles Hitsman
Rehabilitation Specialist
City of Charlotte
Neighborhood and Business Services
600 E. Trade St.
Charlotte, NC 29202

PH: (704) 336 3495 Fax: (704) 336-3489



CITY OF CHARLOTTE

NEIGHBORHOOD & BUSINESS SERVICES

Instructions to Bidders

Explanations to Bidders

Any explanation desired by a Contractor regarding the meaning or interpretation of the advertisement for bids, drawings, specifications, etc., must be requested in writing to the Rehabilitation Specialist with sufficient time allowed for a reply to each Contractor before the submission of their bids. Any interpretation made will be in the form of an addendum to the invitation for bids, drawings, specifications, etc., and will be furnished to all prospective Contractors. The Contractor must acknowledge any revision to the bid documents in the space provided on the bid form and it must be submitted with their bid package.

Preparation of Bids

Bids shall be submitted on the forms furnished, or copies thereof, and must be manually signed. If erasures or other changes appear on the forms, the person signing the bids must initial each erasure or change

- The Contractor's Bid Proposal must be properly executed and submitted on the form provided. Bids by Contractors must be received by the Rehabilitation Specialist at the time and place specified on the "Invitation to Bid"
- No bid will be considered unless all individual work items on the Bid Form including any addendums are priced. The sum of all work items must equal to the Total Bid Amount.
- Unless called for, alternate bids will not be considered
- Modification of bids already submitted will be considered if received at the office designated in the invitation for bids by the time set for opening of bids

Submittal of Bids

- Sealed bids will be submitted to the Safe Home Program Office as directed in the invitation to bid prior to or at the appointed bid opening time
- Bid will be time stamped on the date of delivery
- Each bid must be submitted in a sealed envelope bearing on the outside the name of the Contractor, the name of the project for which the bid is submitted, and the date and time of the bid opening
- All bids submitted must be typed or written in ink and signed by the Contractor's designated representative

G:\SELECTIVE REHAB TEAM\forms\bid forms and documents\Invitation to bid WARREN



CITY OF CHARLOTTE

NEIGHBORHOOD & BUSINESS SERVICES

- Failure to include all forms may result in rejection of a bid
- Required Bid Package Forms:
 - o Scope of Work
 - o Addenda Acknowledgement
 - o Itemized Work Sheet
 - o Subcontractor Certifications (if applicable)

NEIGHBORHOOD & BUSINESS SERVICES

http://housing.charlottenc.gov | 600 E. Trade Street | Charlotte, NC

Prepared By:
City of Charlotte Housing & Neighborhood Services
600 E. Trade Street
Charlotte, NC 28202
(704) 336-7600

	Property Details			•	distribution of the
	Address:	1836 Irma St	Owner:	Linda Moore	
		Charlotte, NC 28216	Owner Phone:	Cell: (704) 712-608	32
	Structure Type:	Single Unit	Program(s):	Targeted FY18 (CI	OBG Funds)
	Square Feet:	904			
	Year Built:	1983			
	Property Value:	52700			
	Tax Parcel:	07505101			
	Census Tract:				
	Property Zone:	Council District 2			
1	<u>Description</u> Portable Toilet	0.0 General Requirements t facilities from job start until approval of p	ermanent facilities. Bid Cost:Base	Floor Room X Quantity	Exterior Total Cost
2	Permits Required The contractor is respo	nsible obtaining and paying for all permits	required. Said permits	shall include all items	s in this scope of work.
3	Dumpster After procuring all requ debris using dust contraway dally using dump		Base Disters as needed without any evidence of the during the during the distribution of the	Quantity It damaging the site, mpsters use, Contract X Quantity	Total Cost Collect construction of the may haul debris Total Cost

	Repair Category: 02.0 Site Improvements				
	Description		Floor	Room	<u>Exterior</u>
C.	Privacy Fence enclosure for trash-cans				
+	Construct a $6 \times 8 \times 6 \times 6$, gated structure. Use white vinyl mat	erial. Locate p	er owners recomn	endation.	,
		Bid Cost:	600 x	(=	600
			Base	Quantity	Total Cost
_	Repair Category: 03.0 Foundation & Crawl Space				Tabana ya Bara a sa Bara sa
•	Description		<u>Floor</u>	<u>Room</u>	<u>Exterior</u>
	Crawl Space Access Door				
	Install a 3/4" pressure treated plywood access door in a 2" x 4"	pressure treat	ed frame. Provide	e galvanized iror	n hinges and hasp.
		Rid Cost:	$\gamma \sim x$	(_	2201
		Dia 0031,	Base	Quantity	してい! Total Cost
/	Repair Category: 08.0 Doors & Windows				m i jaran mu mit
6	Description		Floor	Room	Exterior
	Aluminum Storm Door (2) front and side doors		[190]		
	Install an aluminum combination storm and screen door. Comp	lete with self c	loser and locking	nardware.	
	mistali dii didiilindii oombildoo otom did oo oo oo oo oo				701
		Bid Cost:	_ <u>></u> >∞_x_	=	7.00
_		Bid Cost:	Base	Quantity	フ ひ V Total Cost
7	Vinyl Window	Bid Cost: _	Base	Quantity	Total Cost
7	Vinyl Window Dispose of window units and any security bars. Field measure, windows including half screens. Insulate rough opening. Install Exterior trim to be wrapped in PVC coated aluminum coil as ne installation is to include repairing any damaged header, framing joists and sill.	order and inst new extensior eded. Repair a g (to include ki	all new Energy Stands, casing an I jambs, casing an Ill areas disturbed Ing studs, jack stud	ar rated vinyl, do d sill as needed by removal and ds etc.) sub-floor	ouble glazed LOW- E I, prime and paint. I installation. This r, floor joists, band
7	Dispose of window units and any security bars. Field measure, windows including half screens. Insulate rough opening. Install Exterior trim to be wrapped in PVC coated aluminum coil as ne installation is to include repairing any damaged header, framing	order and inst new extensior eded. Repair a g (to include ki	all new Energy Stands, casing an I jambs, casing an Ill areas disturbed Ing studs, jack stud	ar rated vinyl, do d sill as needed by removal and ds etc.) sub-floor	ouble glazed LOW- E I, prime and paint. I installation. This r, floor joists, band
7	Dispose of window units and any security bars. Field measure, windows including half screens. Insulate rough opening. Install Exterior trim to be wrapped in PVC coated aluminum coil as ne installation is to include repairing any damaged header, framing	order and inst new extensior eded. Repair a g (to include ki	all new Energy Stands, casing an I jambs, casing an Ill areas disturbed Ing studs, jack stud	ar rated vinyl, do d sill as needed by removal and ds etc.) sub-floor	ouble glazed LOW- E I, prime and paint. I installation. This r, floor joists, band
7	Dispose of window units and any security bars. Field measure, windows including half screens. Insulate rough opening. Install Exterior trim to be wrapped in PVC coated aluminum coil as ne installation is to include repairing any damaged header, framing joists and sill.	order and inst new extensior eded. Repair a g (to include ki	all new Energy Stands, casing an I jambs, casing an Ill areas disturbed Ing studs, jack stud	ar rated vinyl, do d sill as needed by removal and ds etc.) sub-floor	ouble glazed LOW- E l, prime and paint. I installation. This
7	Dispose of window units and any security bars. Field measure, windows including half screens. Insulate rough opening. Install Exterior trim to be wrapped in PVC coated aluminum coil as ne installation is to include repairing any damaged header, framing	order and inst new extension eded. Repair a g (to include ki Bid Cost: ergy Star rated wide peep sigl	all new Energy Stands, casing an all areas disturbeding studs, jack students as a Base Pre-hung exterior the New casing an	ar rated vinyl, do d sill as needed by removal and is etc.) sub-floor 1 2 = Quantity door. Insulate c d shoe molding	Total Cost avity. Install mortised will match existing.
7	Dispose of window units and any security bars. Field measure, windows including half screens. Insulate rough opening. Install Exterior trim to be wrapped in PVC coated aluminum coil as ne installation is to include repairing any damaged header, framing joists and sill. 2- Prehung Metal Door Entrance Remove 2 existing doors, frame and threshold. Install new Ene dead bolt and lever handled door hardware keyed alike. Install Apply primer and topcoat. This installation to include repairing	order and inst new extension eded. Repair a g (to include ki Bid Cost: ergy Star rated wide peep sigl any damaged	all new Energy Stands, casing an all areas disturbeding studs, jack studing studs, jack studing students as a studing studing studing an all the ader, door frame	ar rated vinyl, do d sill as needed by removal and ds etc.) sub-floor 2 = Quantity door. Insulate c d shoe molding ing, to include w	Total Cost avity. Install mortised will match existing.
8	Dispose of window units and any security bars. Field measure, windows including half screens. Insulate rough opening. Install Exterior trim to be wrapped in PVC coated aluminum coil as ne installation is to include repairing any damaged header, framing joists and sill. 2- Prehung Metal Door Entrance Remove 2 existing doors, frame and threshold. Install new Ene dead bolt and lever handled door hardware keyed alike. Install Apply primer and topcoat. This installation to include repairing	order and inst new extension eded. Repair a g (to include ki Bid Cost: ergy Star rated wide peep sigl any damaged	all new Energy Stands, casing an all areas disturbeding studs, jack students as a Base Pre-hung exterior the New casing an	ar rated vinyl, do d sill as needed by removal and ds etc.) sub-floor 2 = Quantity door. Insulate c d shoe molding ing, to include w	Total Cost avity. Install mortised will match existing.


Door Hardware Interior - Master Bedroom

Repair door frame / casing

Bld Cost:	70	Х	(_	50	
	Base		Quantity	Total Cost	

Door Hardware Interior - Right middle Bedroom

Repair door frame / casing



Repair Category: 09.0 HVAC

Description

()

11

Floor Room

Exterior

2- Window Air Conditioners, Replace

Install 2 new Window air-conditioning units per the manufacturer's recommendations. Support unit per Owners Manual. Properly dispose of existing unit.

✓ Electric Baseboard Replacement

Remove and replace all electric baseboard heat registrars, sized to heat each individual room appropriately. Repair any wall / floor areas not covered by new registrars.

Bid Cost:
$$\frac{300 \times 5}{200 \times 100} = \frac{1500}{200 \times 100}$$

Repair Category: 10.0 Electrical

<u>Description</u>

Floor Room

Exterior

Light Fixture Replace - Kitchen / Dining Room

Replace (2) ceiling mounted 2 UL approved, LED light fixture with shade and lamps.

Bid Cost:
$$X = S 6 \sim$$
Base Quantity Total Cost

GFCI Receptacle 20 AMP - Kitchen

Install a flush mounted, ground fault circuit interrupted, duplex receptacle and cover plate. Fish wire and repair all tear out as needed.

•	A LED	Screw	Base	Bulb	Installation

Replace all existing screw base (A-Type) lamps throughout the house with LED screw based omnidirectional (A-Type) lamps. Contractor to field verify quantity needed.

Bid Cost: X | = Sv 3

Base Quantity Total Cost

Ceiling Fan with Light Kit - Master bedroom

Install a 52" 3 speed flush mounted ceiling fan with a minimum two bulb UL approved, LED light fixture with shade and lamps. Include ceiling fan mounting box.

Bid Cost: 350 x = 350

Base Quantity Total Cost

Combination CO / Smoke Detector Hard Wired & Smoke Detectors

Install a hard wired combination carbon monoxide and smoke detector with battery back up in hallway. Install a Smoke detector in each bedroom.

Bid Cost: X I = Sto

Ceiling Fan with Light Kit - Right middle Bedroom

Install a 52" 3 speed flush mounted ceiling fan with a minimum two bulb UL approved, LED light fixture with shade and lamps. Include ceiling fan mounting box.

Bid Cost: 3 X = 3 CV

Base Quantity Total Cost

Troubleshoot Electrical System

Communicate with owner. Existing malfunctioning electrical issues to be corrected. Troubleshoot malfunctioning circuit, replace any defective or damaged wiring, devices, and equipment and restore the circuit to safe and proper operation per all requirements of the Electrical Code.

Bid Cost: $\frac{\int \omega_{X}}{Base} = \frac{\int \omega_{S}}{Quantity} = \frac{\int \omega_{S}}{Total Cost}$

Light Fixture Exterior - Front & Side Doors

Replace or install a UL approved, LED light fixture.

Bid Cost: X = 300Base Quantity Total Cost

1	Description		Floor	Room		Exterior
	Rebuild Bathrooms - (2)					
	Rebuild the bathroom complete with all the following features:					
yen No	*ceiling mounted fan vented through the roof *switched light fixture over the vanity *GFCI outlet per Code *3- Grab bars per room * Bath #1 New fiberglass tub shell, tile 3 tub walls to top of the	window , install	ceramic soap dis	sh		
	*Bath #2 , 4 piece fiberglass tub and surround , *Low VOC Semi-gloss paint. walls / ceilings *baseboard and shoe mold at standard locations *1.6 gpf commode, 17" commodes	,	·			
(1)	*24" vanity with cultured marble top and single handle faucet *3 plece bath hardware set (towel bar, paper holder, and towel *mirror over vanity *Resilant Floor Coverings	ring)				
	All materials and construction methods shall meet the requiren	ents of the rele	evant Construction	n Specificatio	ons and th	e NC Codes.
			9700 x			9700
			9700 X Base	/ Quantity		7700 Total Cost
✓	Water Heater 40 Gallon Electric					7700 Total Cost
√	Install a 40 gallon, glass lined, high recovery insulated to R-7, pressure and temperature relief valve, expansion tank, dischare electric supply. If it is located on an upper floor or if there is no	Bid Cost: double elemen	Base t, electric water h in 6" of floor or to	Quantity eater with 10 outside of st) year warı ructure, sh	ranty. Include nut-off valve and
V	Install a 40 gallon, glass lined, high recovery insulated to R-7,	Bid Cost: double elemen ge tube to with floor drain, ins	Base t, electric water h in 6" of floor or to tall a catch pan d	Quantity eater with 10 outside of st rained to the) year warı ructure, sl exterior. (ranty. Include nut-off valve and
✓ ·	Install a 40 gallon, glass lined, high recovery insulated to R-7, pressure and temperature relief valve, expansion tank, dischare electric supply. If it is located on an upper floor or if there is no	Bid Cost: double elemen ge tube to with floor drain, ins	Base t, electric water h in 6" of floor or to	Quantity eater with 10 outside of st rained to the) year warı ructure, sh exterior. [ranty. Include nut-off valve and Dispose of old
V	Install a 40 gallon, glass lined, high recovery insulated to R-7, pressure and temperature relief valve, expansion tank, dischare electric supply. If it is located on an upper floor or if there is no water heater appropriately.	Bid Cost: double elemen ge tube to with floor drain, ins	Base It, electric water hin 6" of floor or to tall a catch pan d	Quantity eater with 10 outside of st rained to the) year warı ructure, sh exterior. [ranty. Include nut-off valve and Dispose of old
	Install a 40 gallon, glass lined, high recovery insulated to R-7, pressure and temperature relief valve, expansion tank, discharelectric supply. If it is located on an upper floor or if there is no water heater appropriately. Repair Category: 12.0 Floor	Bid Cost: double elemen ge tube to with floor drain, ins	Base It, electric water hin 6" of floor or to tall a catch pan d	Quantity eater with 10 outside of st rained to the Quantity) year warı ructure, sh exterior. [ranty. Include nut-off valve and Dispose of old
	Install a 40 gallon, glass lined, high recovery insulated to R-7, pressure and temperature relief valve, expansion tank, dischare electric supply. If it is located on an upper floor or if there is no water heater appropriately. Repair Category: 12.0 Floor Description Resilient Flooring - Kitchen & Dining Room	Bid Cost: double elemen ge tube to with floor drain, ins	Base It, electric water hin 6" of floor or to tall a catch pan d A Base Floo	Quantity eater with 10 outside of st rained to the Quantity Room) year warı ructure, sh exterior. (ranty. Include nut-off valve and Dispose of old /
	Install a 40 gallon, glass lined, high recovery insulated to R-7, pressure and temperature relief valve, expansion tank, dischare electric supply. If it is located on an upper floor or if there is no water heater appropriately. Repair Category: 12.0 Floor Description Resilient Flooring - Kitchen & Dining Room Install 25 year warrantied resilient floor covering per manufact	Bid Cost: double elemen ge tube to with floor drain, ins	Base It, electric water hin 6" of floor or to tall a catch pan d A Base Floo	Quantity eater with 10 outside of st rained to the Quantity Room) year warı ructure, sh exterior. (ranty. Include nut-off valve and Dispose of old /
	Install a 40 gallon, glass lined, high recovery insulated to R-7, pressure and temperature relief valve, expansion tank, dischare electric supply. If it is located on an upper floor or if there is no water heater appropriately. Repair Category: 12.0 Floor Description Resilient Flooring - Kitchen & Dining Room	Bid Cost: double elemen ge tube to with floor drain, ins Bid Cost:	Base It, electric water hin 6" of floor or to tall a catch pan d A Base Floo	Quantity eater with 10 outside of st rained to the Quantity Room) year warı ructure, sh exterior. (ranty. Include nut-off valve and Dispose of old /

Floor System Repair - Bath 1 & 2

Remove all fixtures not built in. Dispose of damaged/unsafe components of floor assembly. Work may include installation of 2"x 10" joists hung 16" on center, plywood or tongue and groove subfloor. Include replacing all deteriorated band joists, wall studs, plates and insulating floor to code.

Bid Cost:	24 vox	(=	2400
	Base	Quantity	Total Cost

Repair Category: 13.0 Interior Wall & Trim

Description

Room

Prep & Paint Room Flat (Right-middle bedroom)

Remove or cover hardware and accessories not to be painted. Scrape loose, peeling, cracked and blistered areas. Clean oil, grease, fungus, dirt, and dust from surfaces. Fill holes and cracks. Prime all new materials and spot prime existing with acrylic latex. Top coat with owner's choice of low VOC acrylic FLAT latex. Painting shall include walls and any associated trim with SEMI-GLOSS latex. Replace or uncover hardware, fixtures and accessories. Any moving of furniture required shall be included.

Bid Cost:	450 x	l <u>=</u>	450
	Base	Quantity	Total Cost

Repair Category: 14.0 Ceiling

Description

Room

Exterior

Ceiling Repair

Repair ceiling finish.

Large crack at dining room / kitchen / living room.

Patch drywall or plaster holes in ceiling greater than one inch. All others use an adhesive mesh and mud over mesh with the appropriate material. Wet sand and smooth.

Prep & Paint Ceiling (Kitchen / Dining Room / Living room / Hall

Remove or cover hardware and accessories not to be painted. Scrape loose, peeling, cracked, and blistered areas. Clean oil, grease, fungus, dirt, and dust from surfaces. Fill holes and cracks. Prime all new materials and spot prime existing with acrylic latex. Top coat with Owner's choice of low VOC acrylic flat latex in all habitable rooms and low VOC acrylic semi-gloss latex in kitchen and baths. Replace or uncover hardware, fixtures and accessories. Any moving of furniture required shall be included.

	Repair Category: 20.0 Custom Repairs			
	Description	<u>Floor</u>	Room	<u>Exterior</u>
./	Installation of New Appliance- Kitchen			
8	Matching Appliances Install a new electric, self cleaning stove. Include a 18 cu ft Refrigerator and	electric hood vent,		
	Bld Cost: _	1700x	(=	1700
		Base	Quantity	Total Cost
	Certification			
	Contractor Name: TR GROW		Total Cost:	31,709
	Signature:		Date:	5/9/18